



SANYO Semiconductors NEWS

Announcement Regarding the Discontinuation of MOS IC Products

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

1. Discontinued products

ETR microcomputer LC7232, 7232N, 7233, 7233N, 7230 series

See the affected products list below.

2. Reason for discontinuing

Reduced sales or user demand for these products.

3. Replacement or similar products

LC72321N, 72322N, 72323N Series

4. Date of discontinuation

These products will be discontinued from June 2006.

Affected products list

Affected products	Affected products	Affected products	Affected products	Affected products	Affected products
C7230-8341D	LC7230-8263	LC7230-8306	LC7230-8347	LC7232-8389	LC7232N8418
C7232NXXXG	LC7230-8267	LC7230-8307	LC7230-8349	LC7232-8391	LC7232N8425
C7232-XXXG	LC7230-8268	LC7230-8309	LC7230-8351	LC7232-8394	LC7232N8426
LC7230	LC7230-8270	LC7230-8310	LC7230-8352	LC7232-8396	LC7232N8427
LC7230-8221	LC7230-8271	LC7230-8317	LC7230-8353	LC7232-8397	LC7232N8428
LC7230-8227	LC7230-8272	LC7230-8322	LC7230-8355	LC7232-8401	LC7232N8429
LC7230-8231	LC7230-8275	LC7230-8323	LC7230-8359	LC7232-8403	LC7232N8430
LC7230-8232	LC7230-8276	LC7230-8328	LC7230-8370	LC7232-8407	LC7232N8433
LC7230-8233	LC7230-8277	LC7230-8331	LC7230-8374	LC7232-8408	LC7232N8434
LC7230-8236	LC7230-8278	LC7230-8334	LC7230-XXX	LC7232-8409	LC7232N8435
LC7230-8238	LC7230-8283	LC7230-8335	LC7232-8291	LC7232-8410	LC7232N8437
LC7230-8239	LC7230-8284	LC7230-8337	LC7232-8366	LC7232-8414	LC7232N8438
LC7230-8240	LC7230-8285	LC7230-8339	LC7232-8373	LC7232-8417	LC7232N8439
LC7230-8244	LC7230-8287	LC7230-8340	LC7232-8375	LC7232-8419	LC7232N8440
LC7230-8251	LC7230-8288	LC7230-8341	LC7232-8376	LC7232-8421	LC7232N8442
LC7230-8256	LC7230-8300	LC7230-8342	LC7232-8377	LC7232-8424	LC7232N8443
LC7230-8257	LC7230-8301	LC7230-8343	LC7232-8380	LC7232A	LC7232N8444
LC7230-8258	LC7230-8303	LC7230-8345	LC7232-8382	LC7232N8412	LC7232N8445
LC7230-8259	LC7230-8305	LC7230-8346	LC7232-8385	LC7232N8416	LC7232N8446

Continued on next page.

SANYO Semiconductor Co., Ltd.

TOKYO OFFICE Tokyo Bldg., 1-10, 1 Chome, Ueno, Taito-ku, TOKYO, 110-8534 JAPAN

Continued from preceding page.

Affected products	Affected products	Affected products	Affected products	Affected products	Affected products
LC7232N8452	LC7232N8801	LC7232N8901	LC7233N8879	LC7232N8812	LC7233N8831
LC7232N8453	LC7232N8802	LC7232N8906	LC7233N8880	LC7232N8819	LC7233N8841
LC7232N8454	LC7232N8803	LC7232N8907	LC7233N8883	LC7232N8824	LC7233N8844
LC7232N8455	LC7232N8806	LC7232N8911	LC7233N8885	LC7232N8827	LC7233N8849
LC7232N8459	LC7232N8807	LC7232N8927	LC7233N8886	LC7232N8836	LC7233N8850
LC7232N8461	LC7232N8808	LC7232N8938	LC7233N8887	LC7232N8848	LC7233N8852
LC7232N8462	LC7232N8810	LC7232N8939	LC7233N8889	LC7232N8873	LC7233N8857
LC7232N8463	LC7232N8813	LC7232N8947	LC7233N8893	LC7232N8874	LC7233N8861
LC7232N8464	LC7232N8815	LC7232N8961	LC7233N8894	LC7232N8900	LC7233N8864
LC7232N8465	LC7232N8816	LC7232N8970	LC7233N8899	LC7232N8902	LC7233N8866
LC7232N8466	LC7232N8821	LC7232N8971	LC7233N8929	LC7232N8913	LC7233N8867
LC7232N8467	LC7232N8829	LC7232N8981	LC7233N8930	LC7232N8925	LC7233N8903
LC7232N8468	LC7232N8832	LC7232N9200	LC7233N8931	LC7232N8941	LC7233N8956
LC7232N8469	LC7232N8834	LC7232N9208	LC7233N8942	LC7232N8967	LC7233N8965
LC7232N8471	LC7232N8837	LC7232N9221	LC7233N8944	LC7232N8985	LC7233N8974
LC7232N8472	LC7232N8840	LC7232N9232	LC7233N8946	LC7232N9219	LC7233N8987
LC7232N8474	LC7232N8842	LC7232N9240	LC7233N8949	LC7232N9224	LC7233N8993
LC7232N8475	LC7232N8843	LC7232N9248	LC7233N8960	LC7232N9269	LC7233N8994
LC7232N8477	LC7232N8847	LC7232N9293	LC7233N8972	LC7233N8420	LC7233N9213
LC7232N8482	LC7232N8854	LC7232N9372	LC7233N8973	LC7233N8448	LC7233N9228
LC7232N8484	LC7232N8855	LC7232NXXXX	LC7233N9206	LC7233N8451	LC7233N9266
LC7232N8485	LC7232N8859	LC7232-XXXX	LC7233N9207	LC7233N8456	LC7233N9322
LC7232N8486	LC7232N8863	LC7233N8818	LC7233N9222	LC7233N8476	LC7233N9331
LC7232N8487	LC7232N8875	LC7233N8853	LC7233N9306	LC7233N8483	LC7233N9334
LC7232N8488	LC7232N8876	LC7233N8856	LC7233N9311	LC7233N8493	LC7233N9367
LC7232N8489	LC7232N8878	LC7233N8858	LC7233N9959	LC7233N8494	LC7233N9376
LC7232N8491	LC7232N8882	LC7233N8862	LC7233N-XXX	LC7233N8805	LC7233N9409
LC7232N8492	LC7232N8890	LC7233N8868	LC7233NXXXG	LC7233N8814	LC7233N9414
LC7232N8497	LC7232N8892	LC7233N8870	LC7233-XXX	LC7233N8820	
LC7232N8800	LC7232N8898	LC7233N8871	LC7232N8811	LC7233N8822	

Please contact your SANYO semiconductor sales representative if you have any questions or need any technical documentation.