



SANYO Semiconductors NEWS

Announcement Regarding the Discontinuation of Thick Film IC Products

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

Date of discontinuation : December 1995

Replacement products : None

Affected products

Discontinued products	Discontinued products	Discontinued products	Discontinued products
STK0025	STK024	STK083G	STK2038
STK0029	STK025	STK084	STK2038M
STK0029N	STK027	STK084G	STK2038MK4
STK0030	STK0292	STK085-105	STK2040
STK0035	STK031	STK086	STK2048MK2
STK0035N	STK032	STK086G	STK2048MK4
STK0039	STK035	STK086G-1	STK2058MK4
STK0039N	STK0352	STK089	STK2068MK2
STK0040	STK036	STK090	STK2101
STK0040K	STK040	STK1030	STK2101N
STK0040MK2	STK0401	STK1035	STK2110
STK0049	STK043	STK1035Z	STK2110C
STK0049S	STK043-105	STK1039	STK2110CX
STK0050	STK0452	STK1040	STK2110T
STK0050MK2	STK050	STK1045	STK2125
STK0050N	STK056	STK1049	STK2129
STK0055NV	STK067	STK1049Z	STK2129S
STK0059	STK070	STK1050	STK2135S
STK0060	STK071	STK1050A	STK2139M
STK0060A	STK075	STK1050AAK	STK2145
STK0060MK2	STK075G	STK1050AK	STK2155
STK0070	STK077	STK1050MK2	STK2200
STK0070MK2	STK077-105	STK1060	STK2200C
STK0080	STK077G	STK1060K	STK2200T
STK0080A	STK078	STK1060MK2	STK2230
STK0080ASA	STK078-105	STK1070	STK2240
STK0080MK2	STK078G	STK1070A	STK2240S
STK0100	STK080	STK1070MK2	STK2240SL-U
STK0100MK2	STK080-105	STK1080MK2	STK2250
STK0105	STK080G	STK1101	STK2250N
STK011	STK080GM	STK2025M	STK2250Y
STK013	STK080-105Y	STK2028	STK2260
STK014	STK082	STK2028B	STK2735B
STK015	STK082-105	STK2028BM	STK3041A
STK016	STK082G	STK2028MK2	STK3042
STK0182	STK082GD	STK2029K	STK3042A
STK020	STK082GK	STK2029M	STK3042AAK
STK022	STK082GSL	STK2030	STK3042AK

Continued on next page

SANYO Semiconductor Co., Ltd.

TOKYO OFFICE Tokyo Bldg., 1-10, 1 Chome, Ueno, Taito-ku, TOKYO, 110-8534 JAPAN

Announcement Regarding the Discontinuation of Thick Film IC Products

From preceding page

Discontinued products	Discontinued products	Discontinued products	Discontinued products
STK3042MK2	STK4028	STK4177MK2	STK463SLY
STK3042MK2A	STK4036	STK4180MK2G	STK465
STK3044	STK4060	STK4181	STK465K
STK3056	STK4101MK2	STK4181MK2	STK465M
STK3061Y	STK4110MK2	STK4184MK2	STK465SA
STK3062	STK4111	STK4184MK5	STK4773
STK3062A	STK4111MK2	STK4184MK5K	STK4793
STK3062MK2	STK4120MK2	STK4185MK2	STK4793TV
STK3062MK2A	STK4120MK2G	STK4187MK2	STK4803
STK3062MK4	STK4120MK5	STK4190MK2G	STK4803M
STK3076	STK4121	STK4191	STK4813
STK3081Y	STK4121MK2	STK4191MK2	STK4833
STK3082	STK4121MK2M	STK4191MK2G	STK4833AK
STK3082A	STK4127MK2	STK4191MK2GS	STK4833M
STK3082MK2	STK4130MK2	STK4191MK2V	STK4843
STK3082MK2A	STK4130MK5	STK4194MK5	STK4853
STK3101Y	STK4131	STK4195MK5	STK4853Y
STK3102	STK4131M	STK4197MK2	STK4863
STK3102MK2A	STK4131MK2	STK4204MK2	STK4873
STK3102MK4	STK4131MK2M	STK4204MK5	STK4873Y
STK3106	STK4137MK2	STK4205MK2	STK4893
STK3156	STK4140MK2	STK4214MK2	STK4913
STK3161	STK4140MK2G	STK4214MK5	STK4913S
STK3161B	STK4140MK5	STK4215MK2	STK4913SN
STK3161BT	STK4141	STK4224MK5	STK6316
STK3375	STK4141MK2	STK4225MK2	STK6324A
STK3375AT	STK4141MK2GS	STK4234MK2	STK6324AT
STK3375ATS	STK4141S	STK4234MK5	STK6324B
STK3375B	STK4141MK2M	STK4235MK2	STK6324BT
STK3375BT	STK4141MK2SP	STK4272	STK6324C
STK3375D	STK4144MK2	STK4273	STK6324CT
STK3375DS	STK4144MK5	STK4273-G	STK6325A
STK3375SA	STK4145MK2	STK430	STK6325B
STK3400A	STK4145MK5	STK430MK2	STK6325C
STK3400B	STK4147MK2SH	STK430MK3	STK6327A
STK3400C	STK415	STK430MK4	STK6328A
STK3400E	STK4150MK2	STK4301	STK8040
STK3400M	STK4150MK2G	STK4301S	STK8050
STK3401	STK4151	STK4311	STK8250
STK3402	STK4151MK2	STK4311S	STK8250MK2
STK3404	STK4154MK2	STK433-105	STK8260MK2
STK3405	STK4154MK2K	STK435-105	STK8270
STK3537	STK4154MK5	STK435AM	STK8270MK2
STK3547	STK4155MK2	STK435SH	STK8280
STK3570	STK4155MK5	STK436-105	STK8280MK2
STK3571	STK4157MK2	STK436TV	STK8455
STK3573	STK4160MK2	STK436TV115	STK8460MK2
STK3600	STK4160MK2G	STK437-105	STK8500
STK3605C	STK4161	STK437TV	STK8510
STK4017	STK4161MK2	STK441-105	STK8600MK2
STK4017C	STK4164MK2	STK443	STK8600MK2E
STK4019	STK4164MK5	STK4544MK5	STK8605MK2
STK4019M	STK4165MK2	STK460	STK8770MK2
STK4021	STK4167MK2	STK460A	STK8800MK2
STK4023	STK4170MK2G	STK460S	STK6001
STK4024	STK4171	STK463	STK6002
STK4025	STK4171MK2	STK463A	STK6004C
STK4026	STK4171MK2V	STK463N	STK6004C-1
STK4026S	STK4174MK2	STK463S	STK6005D

Continued on next page

Announcement Regarding the Discontinuation of Thick Film IC Products

From preceding page

Discontinued products	Discontinued products	Discontinued products	Discontinued products
STK6005D-1	STK6732C	STK5632D	STK73606
STK6005E	STK6742	STK5633F	STK73802
STK6008	STK6742C	STK571C	STK7406N
STK6008M	STK6762	STK571F	STK7452
STK6009	STK6763	STK5725	STK7453
STK6021	STK6922	STK583F	STK7458
STK611A-2	STK6922S	STK5883FS	STK7459
STK612A-2	STK6932	STK7061	STK7462
STK613A-2	STK6942	STK710-470	STK7468
STK621	STK6942B	STK710-480	STK7551
STK622	STK6952	STK7102	STK7553
STK6303S	STK6962	STK711	STK7554
STK6303S-1	STK6962C	STK711-430	STK760
STK65020MK2Y	STK6962CL	STK711-470	STK761
STK65020MK3	STK6962CLM	STK711-480	STK762
STK65020MK3B	STK6962H	STK711-490	STK7677
STK65030MK2	STK6965	STK7120	STK770
STK65030MK2T	STK6966	STK7200	STK77014E
STK65030MK2Y	STK6972	STK7201	STK7702
STK65031	STK6972C	STK7216	STK77024E
STK65031MK2	STK6872H	STK7217	STK7703
STK65032MK2	STK6981B	STK7218	STK7705
STK65032MK2J	STK6981BLL	STK7221	STK7707-ST
STK65040MK2D	STK6981BZ	STK7225	STK7709-ST
STK65041MK2H	STK6981H	STK7226	STK772
STK65041MK3H	STK6982	STK7231	STK772B
STK65041MK3M	STK6982B	STK7232-SS	STK78501
STK65042MK2	STK6982BC	STK7232-ST	STK78502
STK65042MK2M	STK6982E	STK7233	STK78503
STK65042MK2S	STK6982H	STK7241	STK78518L
STK65042MK2Y	STK6982HF2	STK7250	STK78602
STK65042MK3B	STK6982HMK2	STK7251	STK78603
STK65043MK3	STK6982HMK4-B	STK7252	STK78605F
STK65050MK2	STK6990	STK7252B	STK78617
STK65050MK2M	STK6990-1	STK7253	
STK65051MK2	STK509	STK7271	
STK65051MK3M	STK51422A	STK73012	
STK65051MK3Y	STK51427A	STK7308	
STK65055MK3Y	STK5332	STK7309	
STK65060MK2DD	STK5337	STK7310	
STK65060MK2D	STK5338	STK7310MB	
STK65060MK3M	STK5342	STK73405MK2	
STK65060MK2DB	STK5343	STK73405MK3	
STK65060MK2DC	STK5372H	STK73408MK2	
STK65065MK3	STK541	STK73408MK4	
STK6601	STK542	STK73408MK2-I	
STK6605	STK5441	STK73408MK4TV	
STK6607	STK5441S	STK73410	
STK6712BMK2	STK5445	STK73410MK2	
STK6713AMK2	STK5446	STK73410TV	
STK6713BMK2	STK5473	STK73412TV	
STK6722H	STK5482	STK7348	
STK6722H-O	STK5488	STK7348F	
STK6722H-Z	STK561F	STK7350	
STK6722H-ZA	STK563A	STK7356	
STK6722HL	STK563F	STK7358	
STK6723H-Z	STK5631A	STK7359	
STK6723HZST	STK5631C	STK7360	
STK6732	STK5631F	STK73605	